

QUALITY **CLASSIFICATION**


For the open pallet exchange pool











NOT USABLE

Without being repaired, pallets with these faults must not be used in the open pallet exchange pool



No skewed blocks

Hammering down projecting fastening elements



Drying/cleaning soaked boards





(EPAL, UIC, EUR possible)

REPAIR only permitted by duly licensed repair company:



Missing component



Visible fastening elements e.g. nails



Inadmissible component e.g. under-dimensioned, woodwo



Contaminations which can be passed onto the products e.g. paint, oil, smell, mould stains at



Stringer, partially or fully fractured board



Inadmissible repair



Skewed block > 1cm



No longer any prescribed identification legible